City of Eugene

Planning & Development
Building and Permit Services

Permit Number: 21-07253-01

Address: 475 E BROADWAY AVE

Project Description: Ph#1 - Site Utilities + Foundation - Includes SOG, Concrete Columns/Podium for Apartments, and Foundation for Parking Structure up to Level 3

Application Type: Commercial Status: Issued

Scope of Work: Phased Permit Zoning: Community Commercial District

Map: 17-03-32-23 Tax Lot: 02600

Subdivision: Addition: Lot: Block:

 Date Received:
 09/17/21
 # Bedrooms:
 685

 Commitment Date:
 11/19/21
 # Dwelling Units:
 246

Ready to issue as of: 08/23/22 In Flood Plain:

Project Coordinator: Erik Swinney **Phone:** 541-682-5372

Sign Standards:

BUILDING CHARACTERISTICS

Construction Types: 1AS Construction Type Comments:

3AS

Occupancy Types: R2 Occupancy Type Comments:

Level 6 = 228

Level 7 = 735

3311 Separated Building: Yes

Fire Sprinklers: Yes Required NFPA 13

Fire Alarms: Yes Required

Building Area: 422567 Number of Stories: 7
Comment: See Sheet 07_G2.00a for Area Tabulation...

Bldg A (Constr Type/Occ)...

3A/R-2 = 181,210sf * \$143.25/sf = \$25,958,332

Bldg B (Constr Type/Occ)...

1A/B = 4,949sf * \$212.46/sf = \$1,051,464 1A/R-2 = 51567sf * 179.04/sf = \$9,232,555 1A/S-2 = 99,708sf * \$115.37/sf = \$11,503,311 3A/R-2 = 76,990sf * \$143.25/sf = \$11,028,817 3A/A-3 = 8,143sf * \$163.01/sf = \$1,327,390

Total \$60,101,869.

Phase 1 = \$10,302,303 (per application) Phase 2 = \$49,799,566 (difference)

Floor Areas (sq ft):

Occupancy Load:

Page 1 of 13 Date: 3/18/2023

Floor	Existing Floor Area	New Floor Area	Total Area
1st Floor	0	68727	68727
2nd Floor	0	67094	67094
3rd Floor	0	67688	67688
4th Floor	0	67688	67688
5th Floor	0	67688	67688
6th Floor	0	45654	45654
7th Floor	0	38028	38028

Existing floor area may not be shown.

	CONTRACTOR DATA
Туре	Contractor
Building	LANDMARK URBAN CONSTRUCTION OR LLC
Electric	NEW REYNOLDS ELECTRIC INC
Mechanical	JET INDUSTRIES INC
Plumbing	HARVEY & PRICE CO
Primary Contact	HAGEROTT DONNA

PLAN REVIEW SUMMARY

CONTRACTOR DATA

Plan review data displayed is the most current for each review. The applicant will receive notification of all issues needing additional information after all reviews on a project have been completed. Supplemental Information (SI) can be submitted prior to or after permit issuance. If you have any questions regarding your project, contact EFSwinney at 541-682-5372 or send email to erik.f.swinney@ci.eugene.or.us. Also note that some reviews (i.e., fire alarms, fire sprinklers) are deferred submittals and will be reviewed after original permit(s) have been issued.

Status Definitions

Pending = Review has not been started

Review = Under review

Waiting = Review for individual review has been completed, waiting for a response External Wait = All reviews for project have been completed, waiting for a response

Approved = Review has been approved

Information = Information only, review not approved

Denied = Project cannot be approved as submitted

For information regarding the review of your project or the commitment date for completion of review, please contact your project coordinator, EFSwinney, at erik.f.swinney@ci.eugene.or.us or by phone at 541 -682-5372.

Plan Review	Status	Review Completion Date
Project Coordination, Application Submittal	Approved	02/22/22
Pre Issuance Coord, Pre Issuance SI	Approved	05/16/22
Post Issuance Coord, Post Issuance SI	Approved	01/26/23
Deferred Coordination, Deferred Submittal	Approved	01/26/23
Building, Application Submittal	Approved	01/13/23
Building, Pre Issuance SI	Approved	01/13/22
Building, Post Issuance SI	Approved	12/06/22
Building, Deferred Submittal	Waiting for info	10/07/22
Structural, Application Submittal	Waiting for info	11/18/21
Structural, Pre Issuance SI	Approved	05/16/22
Structural, Post Issuance SI	Approved	03/17/23
Structural, Deferred Submittal	Approved	01/23/23
Mechanical, Application Submittal	Information	11/19/21

Page 2 of 13 Date: 3/18/2023

Mechanical, Post Issuance SI	Information	11/04/22
Electrical, Post Issuance SI	Approved	11/03/22
Plumbing, Application Submittal	Approved	03/08/22
Plumbing, Post Issuance SI	Approved	10/28/22
Zoning, Application Submittal	Approved	11/17/21
Engineering, Application Submittal	Waiting for info	06/28/22
Engineering, Pre Issuance SI	Approved	02/03/22
Stormwater Standards, Application Submittal	Information	
Stormwater Standards, Pre Issuance SI	Waiting for info	01/13/22
Stormwater Standards, Post Issuance SI	Approved	07/21/22
SDC, Application Submittal	Information	
Fire Marshal, Application Submittal	Approved	10/13/21
Fire Marshal, Post Issuance SI	Approved	11/02/22
A M & M, Application Submittal	Approved	01/13/23
Erosion Prevention, Application Submittal	Approved	03/18/22
Fire Alarm Plans, Deferred Submittal	Pending	
Fire Sprinkler Plans, Deferred Submittal	Waiting for info	01/18/23
Water Main/Hydrant, Deferred Submittal	Approved	10/31/22

PERMITS AND INSPECTIONS							
Permit Type	Status	Issued Date	Expiration Date	Completion Date			
Building	Active	04/06/22	03/11/24				
Inspection	Result	Inspected	Inspector	Comment			
103 Footing	Info Only	05/20/22	JAJohannesen	discussed crane footing. we dont need to inspect it.			
103 Footing	Cancelled	07/18/22	IVRUser				
103 Footing	Reviewed	07/19/22	JAJohannesen	elevator pit footings lines 11.3-12.3 @ L-M area C?			
103 Footing	Reviewed	07/28/22	JAJohannesen	footing OK lines 11.5-15.4@j.4-k.6 approx. OK pending SPI			
103 Footing	Reviewed	08/03/22	RZSteiner	Continuous and pad footings within E line to J.2 and 12 line to 15.5 pending SPI			
103 Footing	Reviewed	08/12/22	JAJohannesen	retaining wall footings line 18@d.3-g.2 ,d.3@16-18, pad footings 17@d.3-j approx. OK after one pad thickened and rebar clearances are met at line d.3 footing steps. at line 16-17. OK pending SPI			
103 Footing	Cancelled	08/15/22	RZSteiner	Wrong code.			
103 Footing	Reviewed	08/17/22	JAJohannesen	reviewed lowest level columns lines 17- 18 @ d.3-g.8 approx			
103 Footing	Reviewed	08/29/22	JAJohannesen	pad footings at east area, south area OK pending SPI			
103 Footing	Reviewed	09/02/22	JAJohannesen	pad footings line 11 @ e-k			
103 Footing	Reviewed	09/16/22	JAJohannesen	ground level core walls lines6.4-6.8@b-b.8, columns ground level line 12@b.3, 12@c ok pending SPI			
103 Footing	Reviewed	09/22/22	JAJohannesen	footing OK b.9-H@ 8.5-11 approx			
103 Footing	Reviewed	09/22/22	JAJohannesen	footings as noted on the request OK after SPI approves them.			
103 Footing	Reviewed	09/29/22	JAJohannesen	perimeter walls at south area reviewed, some bars missing SPI to verify.			
103 Footing	Reviewed	10/06/22	JAJohannesen	perimeter stemwalls around the curved area.			
103 Footing	Reviewed	11/04/22	JAJohannesen	Slab on Grade lines 10.5-12.5 @ A-E, 6-8 @ C-H, 1-2 @ D-E OK after SPI approves			

103 Footing	Needed			
105 Elec Rebar Gre	ound Needed			
108 Foundation	Info Only	05/20/22	JAJohannesen	discussed crane footing. we dont need to inspect it.
108 Foundation	Reviewed	06/16/22	JAJohannesen	reviewed footings lines 15-16 @ G.7-J. OK pending special inspection.
108 Foundation	Reviewed	07/12/22	JAJohannesen	Columns level 1 lines 15-16 @ G.7-J Ok pending SPI
108 Foundation	Cancelled	07/15/22	JAJohannesen	will re schedule for next week when closer to the concrete pour date.
108 Foundation	Reviewed	07/19/22	JAJohannesen	elevator pit footings lines 11.3-12.3 @ L-M area C?
108 Foundation	Reviewed	07/26/22	JAJohannesen	shearwall basement level line d.3 @ 12. -13.8. approx. columns line 12.6@e.8, 15@e.8, 15@d.3. ok pending SPI
108 Foundation	Reviewed	07/29/22	JAJohannesen	footings lines 2-2.7@A.7-C ok pending SPI
108 Foundation	Cancelled	08/09/22	RZSteiner	Wrong code. Needed shear wall
108 Foundation	Reviewed	08/18/22	JAJohannesen	footing 11-12 @ a.7-c
108 Foundation	Reviewed	08/25/22	JAJohannesen	reviewed line D.3 @ 15.5-18. OK pendin SPI
108 Foundation	Reviewed	09/01/22	JAJohannesen	reviewed footing lines 6.4-7.5@a.8-c.2, looked at slab on grade 12-15.5@d.2@j.5 and a few columns
108 Foundation	Reviewed	09/06/22	JAJohannesen	reviewed footings, okper spi
108 Foundation	Reviewed	09/15/22	JAJohannesen	walls ground level lines 7-7.4@B-B.8
108 Foundation	Reviewed	09/26/22	JAJohannesen	areas not ready yet.
108 Foundation	Reviewed	09/27/22	JAJohannesen	footings lines J-K.3@ 15.5-18 approx
108 Foundation	Reviewed	09/29/22	JAJohannesen	perimeter walls at south area reviewed, some bars missing SPI to verify.
108 Foundation	Reviewed	12/28/22	RZSteiner	Zone 4 W. and N. foundation walls only.
108 Foundation	Reviewed	01/13/23	JAJohannesen	level 1 stemwalls lines 13-14 @ A-A.7 approx ok after rebar clearance is obtained.
108 Foundation	Needed			
109 Foundation Drain/Waterproofing	Needed			
110 Structural Con-	crete Reviewed	07/11/22	JAJohannesen	wall line 15.5 @g.5 -J ok pending SPI
110 Structural Con-	crete Reviewed	08/09/22	RZSteiner	C-3 Columns J5 line 12 to 15. Additional columns ok to pour if Insp. by SPI
110 Structural Con-	crete Reviewed	08/10/22	RZSteiner	Three columns on 12.6 line.
110 Structural Con-	crete Reviewed	10/05/22	JAJohannesen	slab on grade lines j.5-M.5@ 9.5-14 approx
110 Structural Con	crete Reviewed	10/11/22	JAJohannesen	SOG lines 15.5-18@ d.3-k.3, j.5-k.3@12 15.5 approx. OK after special inspector approves.
110 Structural Con-	crete Reviewed	10/14/22	RZSteiner	SOG N to L.5 and 1.8 to 8
110 Structural Con	crete Reviewed	10/18/22	JAJohannesen	footings lines 18.8 @ G.3-H.8, A@3.5-8 pads at 4/B, 5.4/B, E@1-1.8, stemwalls lines A@8-14 approx, 13@ B-D. approx
110 Structural Con	crete Reviewed	10/21/22	JAJohannesen	slab on grade. special inspector OK to approve this pour.
110 Structural Con	crete Reviewed	10/27/22	JAJohannesen	footings reviewed linek f @ 6-7. stemwalls reviewed line a @ 3-5, 18.5 @ F-I approx
110 Structural Con	crete Reviewed	11/03/22	JAJohannesen	PT deck lines 12-18 @ D.3- K.3 except 16-18 @ D.3-f OK pending special inspection.
110 Structural Con	crete Reviewed	11/04/22	JAJohannesen	Slab on Grade lines 10.5-12.5 @ A-E, 6 8 @ C-H, 1-2 @ D-E OK after SPI approves

Page 4 of 13 Date: 3/18/2023

				lovel 2 well lines 12.1@ F. LOV ofter CDL
110 Structural Concrete	Reviewed	11/09/22	JAJohannesen	level 2 wall lines 12.1@ E-J OK after SPI approves
110 Structural Concrete	Reviewed	11/14/22	JAJohannesen	no site visit today, ok for SPI to approve these.
110 Structural Concrete	Reviewed	11/17/22	JAJohannesen	PT deck lines 9.8-14 @ J.2-N approx. OK after SPI approves. Also, I discussed cold weather concreting with Sub contractor. The reinforcing was being covered at the conclusion of the inspection. Frost is anticipated tonight with a low in the 20's.
110 Structural Concrete	Reviewed	11/29/22	JAJohannesen	level 2 deck lines 9.5-13 @A- J.2 approx. reviewed bounday element at lines 11.5 @ L-M approx horizontal infill wall reinforcing needs to terminate in the core of the boundary element as shown on sheet S 3.10
110 Structural Concrete	Reviewed	12/09/22	JAJohannesen	level 3 deck reviewed. j.3-L @11.5-13 approx, 12-18 @ D-K approx. observed several issues that were corrected immediately prior to concrete placement while I was on site, observed that some stud rails were missing at line 12.1 @ J.5 in level 3 deck. contractor was looking for the correct stud rails and will install the proper ones. If they cannot locate the correct ones they may have to substitute them for another and will likely need engineer approval. The special inspector will verify this and document the process.
110 Structural Concrete	Reviewed	12/13/22	JAJohannesen	level 2 core walls lines 11.2-11.8 @ B-B.8 approx ok pending SPI
110 Structural Concrete	Reviewed	12/15/22	JAJohannesen	Footings lines 1-3.2 @ A-E reviewed. Unable to locate special inspector while concrete placement was underway. Reinforcing steel had a few deficiencies including missing rebar, clearance from rebar to grade. These issues were corrected while I was onsite. The ATS anchors in the footings were 1 1/8" instead of the plan specified 1 1/4". The contractor is attempting to find the correct anchors so they can be corrected. Pictures will be taken of the correct anchors once installed. The general contractor was informed that the special inspector needs to be doing continuous special instection for concrete placement as specified on sheet \$0.05.
110 Structural Concrete	Reviewed	12/16/22	JAJohannesen	slab on grade lines 3-8 @ A-F, OK after SPI approves.
110 Structural Concrete	Reviewed	12/29/22	RZSteiner	Level 3 Zone 1 bottom matt only. Pending SPI
110 Structural Concrete	Reviewed	01/04/23	RZSteiner	Shear walls U and W level 3. Pending SPI
110 Structural Concrete	Reviewed	01/05/23	RZSteiner	PT/rebar inspection for zone 3 level 2 deck pending SPI
110 Structural Concrete	Reviewed	01/12/23	JAJohannesen	Slab on grade lines 1-3 @ A-E approx. the dowel bars from the footing were bent over at the time of the inspection at line D @ 2-3. Largo was in the process of fixing this after it was discussed.
110 Structural Concrete	Reviewed	01/20/23	JAJohannesen	level 4 deck in parking garage ok pending SPI
110 Structural Concrete	Reviewed	01/30/23	JAJohannesen	level 2 deck lines 1-4.4 @ A-E

Page 5 of 13 Date: 3/18/2023

110 Structural Concrete Reviewed 02/02/23 JAJohannesen 110 Structural Concrete Reviewed 02/07/23 JAJohannesen 110 Structural Concrete Reviewed 02/17/23 JAJohannesen 110 Structural Concrete Reviewed 02/17/23 JAJohannesen 110 Structural Concrete Reviewed 02/17/23 JAJohannesen 110 Structural Concrete Reviewed 03/10/23 JAJohannesen 118 Framing Reviewed 11/29/22 JAJohannesen 118 Framing Reviewed 12/02/22 JAJohannesen 118 Framing Reviewed 12/02/22 JAJohannesen 118 Framing Reviewed 12/19/22 JAJohannesen 118 Framing Reviewed 01/05/23 RZSteiner 118 Framing Reviewed 01/17/23 JAJohannesen 118 Framing Reviewed 01/17/23 JAJohannesen 118 Framing Reviewed 02/06/23 JAJohannesen 118 Framing Reviewed 02/13/23 JAJo					
110 Structural Concrete Reviewed 02/17/23 JAJohannesen 110 Structural Concrete Reviewed 02/27/23 JAJohannesen 1110 Structural Concrete Reviewed 03/10/23 JAJohannesen 1110 Structural Concrete Reviewed 04/12/2/22 JAJohannesen 1110 Structural Concrete Reviewed 05/10/2/22 JAJohannesen 11110 Inderfloor 1118 Framing 1118 F	110 Structural Concrete	Reviewed	02/02/23	JAJohannesen	shearwall reinforcing steel. noticed that the incorrect size verticle bars and ties were installed. Per sub contractor there is
110 Structural Concrete 1110 Structural Concrete 1110 Structural Concrete 1111 Structural Concrete 1111 Structural Concrete 1111 Structural Concrete 1112 Structural Concrete 1113 Framing 1114 Framing 1115 Reviewed 1116 Underfloor 1118 Framing 1118 Fram	110 Structural Concrete	Reviewed	02/07/23	JAJohannesen	approx. ok after SPI
110 Structural Concrete Reviewed 03/10/23 JAJohannesen SLAB ON GRADE ok in trash compacter area and viscinity 110 Structural Concrete Reviewed 11/29/22 JAJohannesen inspection due to guard not being installed yet. 118 Framing Reviewed 11/29/22 JAJohannesen inspection due to guard not being installed yet. 118 Framing Reviewed 11/20/22 JAJohannesen level 2 floor deck nailing lines 3-9 @ K-N approx. 118 Framing Reviewed 12/05/22 JAJohannesen level 2 floor deck lines 1-3 @ H-J ok level 2 floor sheathing OK lines G-L @ 5.5 approx. 118 Framing Reviewed 12/07/22 JAJohannesen level 2 floor sheathing OK lines G-L @ 5.6 approx. 118 Framing Reviewed 12/14/22 JAJohannesen reviewed level 3 floor sheathing OK lines G-L @ 5.5 approx. 118 Framing Reviewed 12/12/22 JAJohannesen reviewed level 3 floor sheathing OK lines G-L @ 5.5 approx. 118 Framing Reviewed 01/03/23 RZSteiner reviewed level 3 floor sheathing ok lines G-L @ 5.5 s. s. section reviewed level 3 decking nailing line 1-3 @ E-H approx level 3 floor sheathing ok lines G-L @ 5.5 s. s. section level 3 floor sheathing ok lines G-L @ 5.5 s. s. section level 3 floor sheathing ok lines G-L @ 5.5 s. s. section level 3 floor sheathing ok lines G-L @ 5.5 s. s. section level 3 floor sheathing on level 4 area D. S. S. s. section level 3 floor sheathing on level 4 area D. S. S. section level 3 floor sheathing on level 4 area D. S. S. section level 3 floor sheathing on level 4 area D. S. S. section level 3 floor sheathing on level 4 area D. S. S. section level 3 floor sheathing on level 4 area D. S. S. Section level 3 floor sheathing level 3 floor sheathing on level 4 area D. S. S. Section level 3 floor sheathing on level 4 area D. S. S. Section level 3 floor sheathing level 3 floor sheathing and S. S. S. Section level 4 decking nailing reviewed level 5 floor deck nailing blocks with sub contractor. reviewed level 5 floor deck nailing blocks of shiners at blocks. I showed areas to framer and level 5 shiners at blocks. I showed areas to framer and story area shower areas and	110 Structural Concrete	Reviewed	02/17/23	JAJohannesen	SPI approves
110 Structural Concrete Needed 116 Underfloor Needed 117 Structural Concrete Needed 118 Framing Reviewed 11/29/22 JAJohannesen insulation 118 Framing Reviewed 11/30/22 JAJohannesen insulation 118 Framing Reviewed 12/02/22 JAJohannesen insulation 118 Framing Reviewed 12/05/22 JAJohannesen insulation 118 Framing Reviewed 12/05/22 JAJohannesen insulation 118 Framing Reviewed 12/05/22 JAJohannesen insulation in access to the deck to do the inspection due to guard not being insulation in access to the deck to do the inspection due to guard not being insulation in access to the deck to do the inspection due to guard not being insulation in access to the deck to do the inspection due to guard not being insulation in access to the deck to do the inspection due to guard not being insulation in access to the deck to do the inspection due to guard not being insulation. In access to the deck to do the inspection due to guard not being insulation. In access to the deck to do the inspection due to guard not being insulation. In access to the deck to do the inspection due to guard not being insulation. In access to the deck to do the inspection due to guard not being insulation. In access to the deck to do the inspection due to guard not being insulation. In access to the deck to do the inspection due to guard not be feed in spection due to guard not being insulated with subject of Geoff and the value of Indian shall guard and insulation. In access to the deck to do the inspection due to guard not being insulated with sub conference in approx. In access to the deck to do the inspection due to guard not being insulated with sub-ordractor. In access to the deck to do the inspection due to guard not being insulated with sub-ordractor. In access to the deck to do the inspection has paper on the subject of Geoff access and access to the deck to do the subject of Geoff a	110 Structural Concrete	Reviewed	02/27/23	JAJohannesen	
116 Underfloor Insulation 118 Framing Reviewed 11/29/22 JAJohannesen inspection due to guard not being installed yet. 118 Framing Reviewed 11/30/22 JAJohannesen inspection due to guard not being installed yet. 118 Framing Reviewed 12/02/22 JAJohannesen level 2 floor deck nailing lines 3-9 @ K-N approx. 118 Framing Reviewed 12/05/22 JAJohannesen level 2 floor deck insel 1-3 @ H-J ok level 2 floor sheathing OK lines G-L @5.5 -8 approx. 118 Framing Reviewed 12/14/22 JAJohannesen napprox. 118 Framing Reviewed 12/19/22 JAJohannesen reviewed level 3 floor deck insel 1-3 @ H-J ok level 2 floor sheathing OK lines G-L @5.5 -8 approx. 118 Framing Reviewed 12/19/22 JAJohannesen reviewed level 3 floor deck insel 1-3 @ H-J ok level 2 floor sheathing OK lines G-L @5.5 -8 approx. 118 Framing Reviewed 12/19/22 JAJohannesen reviewed level 3 floor decking nailing Partial flor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/105/23 RZSteiner Aftior area D floor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/17/23 JAJohannesen wet of the or area D floor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/17/23 JAJohannesen wet of the or area D floor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/17/23 JAJohannesen wet of the or area D floor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/17/23 JAJohannesen wet of the or area D floor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/17/23 JAJohannesen wet of the or area D floor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/17/23 JAJohannesen wet over areas that need to be nailed with sub contractor. reviewed level 5 floor deck nailing, blocks in stance of the section of t	110 Structural Concrete	Reviewed	03/10/23	JAJohannesen	
Insulation Reviewed 11/29/22 JAJohannesen no access to the deck to do the inspection due to guard not being installed yet. 118 Framing Reviewed 11/30/22 JAJohannesen 118 Framing Reviewed 12/02/22 JAJohannesen 118 Framing Reviewed 12/05/22 JAJohannesen 118 Framing Reviewed 12/07/22 JAJohannesen 118 Framing Reviewed 12/14/22 JAJohannesen 118 Framing Reviewed 12/14/22 JAJohannesen 118 Framing Reviewed 12/19/22 JAJohannesen 118 Framing Reviewed 12/19/22 JAJohannesen 118 Framing Reviewed 101/03/23 RZSteiner 118 Framing Reviewed 101/17/23 JAJohannesen 118 Framing Reviewed 101/23/23 JAJohannesen 118 Framing Reviewed 102/06/23 JAJohannesen 118 Framing Reviewed 102/07/23 JAJohannesen 100 Code Railing level 3 lines 5-9.4 @l.5- 8 approx. 100 reviewed level 3 floor deck insiling level 3 floor decking railing 100 reviewed level 3 floor decking railing 100 reviewed level 3 floor decking 100 re	110 Structural Concrete	Needed			
no access to the deck to do the inspection due to guard not being approx. It is Framing Reviewed 12/05/22 JAJohannesen reviewed level 2 floor deck nailing lines S-9 @ K-N approx. It is Framing Reviewed 01/03/23 JAJohannesen Reviewed level 3 floor deck ingling inspection to end and they agreed level 3 floor deck nailing level serviewed level 3 floor deck nailing end with sub contractor. It is Framing Reviewed 01/17/23 JAJohannesen Reviewed level 3 floor deck nailing inspection to be re-called in for tomorrow. It is Framing Reviewed 02/06/23 JAJohannesen Reviewed level 3 floor deck nailing at sea areas, discussed dywall process at seisming for tub/shower framing, still need areas of secussed dywall process at seisming joint. It is Framing Re	116 Underfloor	Noodod			
118 Framing Reviewed 11/29/22 JAJohannesen inspection due to guard not being installed yet. level 2 floor deck nailing lines 3-9 @ K-N approx. 118 Framing Reviewed 12/02/22 JAJohannesen level 2 floor decking nailing lines 1-5 @ J-K level 2 floor decking nailing lines 1-5 @ J-K level 2 floor decking nailing lines 1-5 @ J-K level 2 floor decking nailing lines 1-5 @ J-K level 2 floor decking nailing lines 1-5 @ J-K level 2 floor decking nailing lines 1-5 @ J-K level 2 floor decking nailing lines 1-5 @ J-K level 2 floor decking nailing lines 6-L @ 5.5 - 8 approx. 118 Framing Reviewed 12/19/22 JAJohannesen reviewed level 3 floor decking nailing Reviewed level 3 floor decking nailing Reviewed level 3 floor decking nailing Partial flor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/05/23 RZSteiner level 4 decking nailing reviewed level 3 floor sheathing level 4 decking nailing reviewed level 5 area D floor sheathing level 4 decking nailing reviewed level 5 area D floor sheathing level 4 decking nailing reviewed level 5 area D floor sheathing level 5 area D floor sheathing level 4 decking nailing reviewed level 5 area D floor sheathing level 5 area	Insulation	iveeded			
118 Framing Reviewed 12/02/22 JAJohannesen level 2 floor decking nailing lines 1-5 @ J-k 118 Framing Reviewed 12/05/22 JAJohannesen level 2 floor deck lines 1-3 @ H-J ok 118 Framing Reviewed 12/14/22 JAJohannesen level 2 floor deck lines 1-3 @ H-J ok 118 Framing Reviewed 12/14/22 JAJohannesen floor deck nailing level 3 lines 5-9.4 @1.5-a approx. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 lines 5-9.4 @1.5-a prox. floor deck nailing level 3 floor decking nailing reviewed level 3 floor decking nailing feviewed level 3 floor decking nailing alines feviewed level 3 floor decking nailing alines feviewed level 3 floor decking nailing alines feviewed level 3 floor decking nailing feviewed level 3 floor decking nailing alines feviewed level 3 floor decking nailing alines feviewed level 3 floor decking nailing na few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Reviewed 01/23/23 JAJohannesen level 1 showed areas to framer and they agreed to fix. 118 Framing Reviewed 02/06/23 JAJohannesen level 1 where there are not hold downs. Looked at shower areas and shear wall nailing in a few areas, di	118 Framing	Reviewed	11/29/22	JAJohannesen	inspection due to guard not being installed yet.
118 Framing Reviewed 12/05/22 JAJohannesen Reviewed 12/07/22 JAJohannesen Reviewed 12/07/22 JAJohannesen Reviewed 12/07/22 JAJohannesen Reviewed 12/14/22 JAJohannesen Reviewed 12/14/22 JAJohannesen Reviewed Reviewed 12/14/22 JAJohannesen Reviewed Reviewed 12/14/22 JAJohannesen Reviewed Reviewed 12/22/22 JAJohannesen Reviewed Reviewed 12/22/22 JAJohannesen Reviewed Reviewed Revel 3 floor decking reviewed Revel 3 decking nailing Reviewed 01/03/23 RZSteiner RZSteiner RZSteiner RZSteiner RZSteiner RZSteiner RRZSteiner RZSteiner RZStei	118 Framing	Reviewed	11/30/22	JAJohannesen	approx
118 Framing Reviewed 12/07/22 JAJohannesen 118 Framing Reviewed 12/14/22 JAJohannesen 118 Framing Reviewed 12/19/22 JAJohannesen 118 Framing Reviewed 12/22/22 JAJohannesen 118 Framing Reviewed 12/22/22 JAJohannesen 118 Framing Reviewed 01/03/23 RZSteiner 118 Framing Reviewed 01/05/23 RZSteiner 118 Framing Reviewed 01/05/23 RZSteiner 118 Framing Reviewed 01/12/23 JAJohannesen 118 Framing Reviewed 01/17/23 JAJohannesen 118 Framing Reviewed 01/17/23 JAJohannesen 118 Framing Reviewed 01/17/23 JAJohannesen 118 Framing Reviewed 01/23/23 JAJohannesen 118 Framing Reviewed 01/23/23 JAJohannesen 118 Framing Reviewed 01/23/23 JAJohannesen 118 Framing Reviewed 02/06/23 JAJohannesen 118 Framing Reviewed 02/07/23 JAJohannesen 118 Framing Reviewed 02/13/23 JAJohannesen 118 Framing Reviewed 02/16/23 JAJohannesen	118 Framing	Reviewed	12/02/22	JAJohannesen	
118 Framing Reviewed 12/14/22 JAJohannesen floor deck nailing level 3 lines 5-9.4 @1.5- n approx. floor deck nailing level 3 lines 5-9.4 @1.5- n approx. floor deck nailing level 3 lines 5-9.4 @1.5- n approx. floor deck nailing level 3 lines 5-9.4 @1.5- n approx. reviewed level 3 floor decking reviewed level 3 floor decking reviewed level 3 decking nailing reviewed level 3 decking nailing reviewed level 3 floor decking reviewed level 3 decking nailing reviewed level 4 area D. S. E. section 118 Framing Reviewed 01/05/23 RZSteiner Althor area D floor sheathing level 4 area D. S. E. section 118 Framing Reviewed 01/12/23 JAJohannesen level 5 area D floor sheathing nailing. Wevel 4 decking nailing reviewed line 1-3 @ E-H approx level 5 area D floor sheathing nailing. Wevel 4 area nailing naili	118 Framing	Reviewed	12/05/22	JAJohannesen	level 2 floor deck lines 1-3 @ H-J ok
118 Framing Reviewed 12/14/22 JAJohannesen floor deck nailing level 3 lines 5-9.4 @1.5 n approx. 118 Framing Reviewed 12/19/22 JAJohannesen reviewed level 3 floor decking reviewed level 3 floor decking nailing reviewed level 3 decking nailing Partial flor sheathing on level 4 area D. S. E. sections are partial flor sheathing on level 4 area D. S. E. sections are partial flor sheathing on level 4 area D. S. E. sections are partial flor sheathing on level 4 area D. S. E. sections are partial flor sheathing on level 4 area D. S. E. sections are partial flor sheathing on level 4 area D. S. E. sections are partial flor sheathing on level 4 area D. S. E. sections are partial flor sheathing on level 4 decking nailing reviewed level 5 floor area D floor sheathing level 4 decking nailing reviewed level 5 area D floor sheathing nailing. Went over areas that need to be nailed with sub contractor. reviewed level 5 floor deck nailing, blocks missing in a few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Reviewed 02/02/23 JAJohannesen looked at a couple units tub/shower areas looked at a couple units tub/shower framing, inspection to be re-called in for tomorrow. reviewed firming behind tubs/showers level 1 where there are not hold downs. Looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. reviewed level 1 tub/shower location framing, still need the SPI report. no site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at area D reviewed. need nailing at AFS on level 1 at the tub locations.	118 Framing	Reviewed	12/07/22	JAJohannesen	
118 Framing Reviewed 12/19/22 JAJohannesen reviewed level 3 floor decking reviewed level 3 decking nailing Partial flor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/03/23 RZSteiner S. E. section 118 Framing Reviewed 01/05/23 RZSteiner 4th floor area D floor sheathing level 4 decking nailing reviewed line 1-3 (@ E-H approx level 5 area D floor sheathing nailing. went over areas that need to be nailed with sub contractor. reviewed level 5 floor deck nailing, blocks missing in a few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Reviewed 02/02/23 JAJohannesen Braming Reviewed 02/06/23 JAJohannesen Graming for tub/shower areas looked at a couple units tub/shower areas to framer and they agreed to fix. 118 Framing Reviewed 02/06/23 JAJohannesen Graming behind tubs/showers level 1 where there are not hold downs. Looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. reviewed level 1 tub/shower looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. reviewed level 1 tub/shower looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. reviewed level 1 tub/shower looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. reviewed level 1 tub/shower looked areas to framer and they agreed to fix. 118 Framing Reviewed 02/16/23 JAJohannesen Reviewed Ivel 1 tub/shower looked areas to framer and they agreed to fix. 218 Framing Reviewed 02/07/23 JAJohannesen Reviewed framing behind tubs/shower sevel 1 tub/shower process at seismic joint. reviewed level 1 tub/shower process at seismic joint. reviewed level 1 tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	12/14/22	JAJohannesen	_
118 Framing Reviewed 01/03/23 RZSteiner Partial flor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/05/23 RZSteiner Hit floor area D floor sheathing on level 4 area D. S. E. section 118 Framing Reviewed 01/12/23 JAJohannesen level 4 decking nailing reviewed line 1-3 @ E-H approx level 5 area D floor sheathing nailing. 118 Framing Reviewed 01/17/23 JAJohannesen level 5 area D floor sheathing nailing. 118 Framing Reviewed 01/17/23 JAJohannesen went over areas that need to be nailed with sub contractor. reviewed level 5 floor deck nailing, blocks missing in a few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Reviewed 02/06/23 JAJohannesen looked at a couple units tub/shower areas looked at a couple units tub/shower framing, inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/07/23 JAJohannesen level 1 where there are not hold downs. Looked at shower areas and shear wall process at seismic joint. 118 Framing Reviewed 02/13/23 JAJohannesen Reviewed Insert and they agreed to fix. 119 Framing Reviewed 02/13/23 JAJohannesen level 1 tub/shower framing inspection to be re-called in for tomorrow. reviewed framing behind tubs/showers level 1 where there are not hold downs. Looked at shower areas and shear wall process at seismic joint. reviewed level 1 tub/shower location framing, still need the SPI report. no site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	12/19/22	JAJohannesen	
118 Framing Reviewed 01/03/23 RZSteiner S. E. section 118 Framing Reviewed 01/05/23 RZSteiner At floor area D floor sheathing elevel 4 decking nailing reviewed line 1-3 © E-H approx level 5 area D floor sheathing nailing. Went over areas that need to be nailed with sub contractor. The floor sheathing nailing area because the floor deck nailing blocks missing in a few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Reviewed 02/06/23 JAJohannesen looked at a couple units tub/shower areas looked at a couple units tub/shower framing. Inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/07/23 JAJohannesen looked at a couple units tub/shower framing inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/13/23 JAJohannesen looked at a couple units tub/shower framing inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/13/23 JAJohannesen looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. 118 Framing Reviewed 02/16/23 JAJohannesen Reviewed level 1 tub/shower location framing. Still need the SPI report. no site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up		Reviewed	12/22/22		
118 Framing Reviewed 01/05/23 RZSteiner S. E. section 118 Framing Reviewed 01/12/23 JAJohannesen Reviewed 01/12/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed Reviewed 01/23/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed Reviewed 01/23/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed 02/06/23 JAJohannesen Reviewed 02/06/23 JAJohannesen Reviewed 02/06/23 JAJohannesen Reviewed 02/06/23 JAJohannesen Reviewed 02/07/23 JAJohannesen Reviewed 02/07/23 JAJohannesen Reviewed 02/07/23 JAJohannesen Reviewed 02/13/23 JAJohannesen Reviewed 02/13/23 JAJohannesen Reviewed Review					
118 Framing Reviewed 01/12/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/17/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed 01/23/23 JAJohannesen Reviewed 02/02/23 JAJohannesen Reviewed 02/06/23 JAJohannesen Reviewed 02/06/23 JAJohannesen Reviewed 02/07/23 JAJohannesen Reviewed 02/07/23 JAJohannesen Reviewed 02/07/23 JAJohannesen Reviewed 02/13/23 JAJohannesen Reviewed 02/16/23 JAJohannesen Reviewed 02/16/23 JAJohannesen Reviewed 02/16/23 JAJohannesen Reviewed 118 Framing Reviewed 02/16/23 JAJohannesen Reviewed 02/16/23 JAJohannesen Reviewed 02/16/23 JAJohannesen Reviewed 118 Framing Reviewed 02/16/23 JAJohannesen Reviewed 02/16/23 JAJohannesen Reviewed 118 Framing Reviewed 02/16/23 JAJohannesen		1 1 1 1			S. E. section
118 Framing Reviewed 01/12/23 JAJohannesen level 5 area D floor sheathing nailing, went over areas that need to be nailed with sub contractor. 118 Framing Reviewed 01/23/23 JAJohannesen lissing in a few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Reviewed 02/06/23 JAJohannesen looked at a couple units tub/shower areas looked at a couple units tub/shower areas looked at a couple units tub/shower framing, inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/07/23 JAJohannesen level 1 where there are not hold downs. Looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. 118 Framing Reviewed 02/16/23 JAJohannesen looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. 118 Framing Reviewed 02/16/23 JAJohannesen looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. 118 Framing Reviewed 02/16/23 JAJohannesen looked at shower areas and shear wall nailing at level 1 tub/shower location framing, still need the SPI report. no site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	01/05/23	RZSteiner	_
118 Framing Reviewed 01/17/23 JAJohannesen went over areas that need to be nailed with sub contractor. Reviewed 01/23/23 JAJohannesen missing in a few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Info Only 02/02/23 JAJohannesen looked at a couple units tub/shower areas looked at a couple units tub/shower framing. inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/07/23 JAJohannesen Reviewed framing behind tubs/showers level 1 where there are not hold downs. Looked at shower areas and shear wall process at seismic joint. 118 Framing Reviewed 02/13/23 JAJohannesen Reviewed level 1 tub/shower location framing. still need the SPI report. no site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	01/12/23	JAJohannesen	@ E-H approx
118 Framing Reviewed 01/23/23 JAJohannesen missing in a few areas and lots of shiners at blocks. I showed areas to framer and they agreed to fix. 118 Framing Info Only 02/02/23 JAJohannesen discussed framing for tub/shower areas looked at a couple units tub/shower framing. inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/07/23 JAJohannesen Praming in spection to be re-called in for tomorrow. 118 Framing Reviewed 02/07/23 JAJohannesen Previewed framing behind tubs/showers level 1 where there are not hold downs. Looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. 118 Framing Reviewed 02/16/23 JAJohannesen Previewed level 1 tub/shower location framing. still need the SPI report. 118 Framing Reviewed 02/21/23 JAJohannesen Provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	01/17/23	JAJohannesen	went over areas that need to be nailed with sub contractor.
Reviewed 02/06/23 JAJohannesen looked at a couple units tub/shower framing. inspection to be re-called in for tomorrow. Reviewed 02/07/23 JAJohannesen reviewed framing behind tubs/showers level 1 where there are not hold downs. Looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. Reviewed 02/16/23 JAJohannesen reviewed level 1 tub/shower location framing. still need the SPI report. Reviewed 02/21/23 JAJohannesen provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	01/23/23		missing in a few areas and lots of shiners at blocks. I showed areas to framer and
118 Framing Reviewed 02/06/23 JAJohannesen framing. inspection to be re-called in for tomorrow. 118 Framing Reviewed 02/07/23 JAJohannesen reviewed framing behind tubs/showers level 1 where there are not hold downs. 118 Framing Reviewed 02/13/23 JAJohannesen JAJohannesen Reviewed drywall process at seismic joint. 118 Framing Reviewed 02/16/23 JAJohannesen JAJohannesen Reviewed level 1 tub/shower location framing. still need the SPI report. 118 Framing Reviewed 02/21/23 JAJohannesen JAJohannesen Reviewed level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Info Only	02/02/23	JAJohannesen	_
Seviewed Oz/07/23 JAJohannesen level 1 where there are not hold downs. Looked at shower areas and shear wall nailing in a few areas, discussed drywall process at seismic joint. Teviewed level 1 tub/shower location framing. Still need the SPI report. No site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. Need 118 Framing Reviewed Oz/27/23 JAJohannesen JAJohannesen Neviewed Oz/27/23	118 Framing	Reviewed	02/06/23	JAJohannesen	framing. inspection to be re-called in for tomorrow.
118 Framing Reviewed O2/13/23 JAJohannesen nailing in a few areas, discussed drywall process at seismic joint. reviewed level 1 tub/shower location framing. still need the SPI report. No site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	02/07/23	JAJohannesen	level 1 where there are not hold downs.
118 Framing Reviewed O2/16/23 JAJonannesen framing. still need the SPI report. no site visit today special inspection has provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	02/13/23	JAJohannesen	nailing in a few areas, discussed drywall
118 Framing Reviewed 02/21/23 JAJohannesen provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock roof sheathing at area D reviewed. need nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	02/16/23	JAJohannesen	framing. still need the SPI report.
118 Framing Reviewed 02/27/23 JAJohannesen nailing at shearwalls and blocking to be touched up	118 Framing	Reviewed	02/21/23	JAJohannesen	provided a report for the shear nailing and ATS on level 1 at the tub locations. OK to proceed with tub/shower pre rock
118 Framing Reviewed 03/06/23 JAJohannesen floor decking nailing level 4 area C oK	_				nailing at shearwalls and blocking to be touched up
	118 Framing	Reviewed	03/06/23	JAJohannesen	floor decking nailing level 4 area C oK

Page 6 of 13 Date: 3/18/2023

118 Framing	Reviewed	03/07/23	JAJohannesen	shearwalls line 9-10 in sector c level 1-3 OK to cover framing at expansion joint side
118 Framing	Reviewed	03/10/23	JAJohannesen	looked at level 1 framing at area A where CMU walls will be build covering the wood framing. lines E.2 @ 1-1.8, 2 @ D-E, D.2@ 2-3, F.2 @ 5.8-8 approx
118 Framing	Cancelled	03/14/23	IVRUser	_, = = = = = = = = = = = = = = = = = =
118 Framing	Reviewed	03/15/23	JAJohannesen	looked at tub locations level 2. not ready yet.
118 Framing	Reviewed	03/17/23	JAJohannesen	areas per inspection request OK
118 Framing	Needed			
920 Waterproofing - Balcony or Sim	Needed			
117 Roof Sheathing	Needed			
	Reviewed	08/15/22	RZSteiner	Wall on 12.1 line E=J lower level.
119 Exterior Shearwall	Reviewed	11/10/22	JAJohannesen	footings reviewed lines 3-8 @ B-F. OK after SPI approves
119 Exterior Shearwall	Reviewed	11/15/22	JAJohannesen	walls not ready yet
119 Exterior Shearwall	Reviewed	11/17/22	JAJohannesen	level 2 shearwalls OK lines 15.5 @ G.5-J, K.3 @ 12-14 approx. OK after SPI approves
119 Exterior Shearwall	Reviewed	02/02/23	JAJohannesen	looked at structural concrete. see entry for str concrete.
119 Exterior Shearwall	Reviewed	02/03/23	JAJohannesen	reviewed level 3-4 wall that was inspected yesterday on line d.3 the boundary element has been OK'd to be reduced in size due to a rebar mix up. an RFI is to follow and will be submitted for review. the verticle rebar has been moved so that it is within the ties.
119 Exterior Shearwall	Reviewed	03/06/23	JAJohannesen	areas noted on the inspection request OK, level 4-5. OK after SPI approves
119 Exterior Shearwall	Needed			
129 Interior Shearwall	Reviewed	08/09/22	RZSteiner	Concrete wall at K3 12.1 to 15
129 Interior Shearwall	Reviewed	08/19/22	JAJohannesen	shearwalls reviewed lines 11.3-11.6@L-L.7, columns line d.3@16,17
129 Interior Shearwall	Reviewed	09/08/22	JAJohannesen	reviewed areas per inspection request
129 Interior Shearwall	Reviewed	11/16/22	JAJohannesen	reviewed concrete shearwall in garage area.
129 Interior Shearwall	Reviewed	11/30/22	JAJohannesen	looked at a few PCC column rebar cages that are underway for level 2
129 Interior Shearwall	Cancelled	01/04/23	RZSteiner	Needed concrete shear walls.
129 Interior Shearwall	Cancelled	01/17/23	JAJohannesen	per contractor
129 Interior Shearwall	Needed			
128 Exterior Lath	Needed			La de la CMII (caracteria la caracteria de la caracteria
127 Masonry Construction	Reviewed	03/15/23	JAJohannesen	reviewed CMU for vehicle barriers in parking garage
127 Masonry Construction	Needed			
120 Wall/Vault Insulation	Reviewed	03/15/23	JAJohannesen	seismic joint areas reviewed.
120 Wall/Vault Insulation	Needed			
130 Lath or Dry Wall	Reviewed	02/24/23	RZSteiner	1st layer behind tubs and some 2nd layer at 2Hr walls. Units 127-139
130 Lath or Dry Wall	Reviewed	03/03/23	RZSteiner	RC channel and gyp behind tubs and shafts. Units 115-119 Two of the units wil require a F/S Eng. judgement for plumbing stacks
130 Lath or Dry Wall	Reviewed	03/14/23	JAJohannesen	reviewed drywall at seismic joints where CMU walls will be built.

130 Lath or Dry Wall	Reviewed	03/17/23	JAJohannesen	level 3 area B firewall reviewed line 10 @ A-A.8 1st layer both sides OK.
130 Lath or Dry Wall	Needed			
131 Firestop	Needed			
Assemblies	Nasalad			
121 Ceiling Grid	Needed			
124 Final Insulation	Needed			
146 Fire Sprinklers	Needed			
147 Alarm Systems	Needed			
144 Emergency Generator	Needed			
153 Water/Hydrant System	Cancelled	01/27/23	ESPhillips- Meadow	contractor canceled
153 Water/Hydrant System	Reviewed	01/31/23	ATBrushett	FDC and fire line have been installed, we need to provide electronic monitoring for the OS&Y valves since they will be in an above ground box. Also need to install a ball drip for the FDC that is accessible. Flush flow and hydro still need to be completed.
153 Water/Hydrant System	Needed			
154 Standpipe	Needed			
143 Fire Regulation	Needed			
150 Landscaping	Needed			Landscaping to be installed per Sheet O5 L3.00
919 Bicycle Parking	Needed			00_20.00
157 Zoning	Needed			All parking spaces marked "Compact" and sidewalk from parking structure to street along S. side of driveway.
160 Emerg Egress Light	Needed			
930 SPI Inspection of Fabricators	Needed			
931 SPI Steel Construction	Needed			
162 SPI Concrete Construction	Needed			
172 SPI Masonry Construction	Needed			
176 SPI Soils	Needed			
174 SPI Sprayed Fireproofing	Needed			
180 SPI Epoxy/Expan/Screw Anchors	Needed			
940 SPI Seismic (Structural Steel)	Needed			
941 SPI Seismic (Structural Wood)	Needed			
944 SPI Seismic(Arch Components)	Needed			
945 SPI Anchorage/Emergency Power	Needed			
955 SPI Anchorage/Vibration Isoltn	Needed			
956 SPI Sprinkler Clearance	Needed			
178 SPI Additional Inspections	Needed			

	Structural rvation	Needed			
	SPI Final Letter	Needed			
199 F	Final Building	Needed			
Electrical		Active	08/23/22	03/11/24	
Inspe	ction	Result	Inspected	Inspector	Comment
210 L Elec	Jndergrnd/Slab	Reviewed	08/24/22	JKGoschie	Zone 1 and 2 deep conduits.
210 L Elec	Jndergrnd/Slab	Reviewed	08/26/22	JKGoschie	Zone 1 and 2. See highlighted plans on site.
210 L Elec	Jndergrnd/Slab	Reviewed	09/12/22	JKGoschie	Main electrical room area.
210 L Elec	Jndergrnd/Slab	Reviewed	09/15/22	JKGoschie	See plan's on site.
210 L Elec	Jndergrnd/Slab	Reviewed	09/19/22	SJLenker	Deep underground conduits running at grid lines 8 & 11 on D line crossing courtyard #2 okay.
Elec	Jndergrnd/Slab	Reviewed	09/27/22	JKGoschie	See plans on site.
Elec	Jndergrnd/Slab	Reviewed	09/28/22	JKGoschie	See plans on site.
Elec	Jndergrnd/Slab	Reviewed	09/30/22	JKGoschie	See plans on site.
Elec	Jndergrnd/Slab	Reviewed	10/07/22	JKGoschie	See plans on site.
Elec	Jndergrnd/Slab	Reviewed	10/25/22	JKGoschie	See plans on site.
Elec	Jndergrnd/Slab	Reviewed	11/02/22	JKGoschie	Level 2 PT deck.
Elec	Jndergrnd/Slab	Reviewed	11/17/22	JKGoschie	Level; 2 zone 1.
Elec	Jndergrnd/Slab	Reviewed	11/29/22	JKGoschie	Level 2 zone 2 PT deck.
Elec	Jndergrnd/Slab	Reviewed	12/08/22	JKGoschie	3 PT deck.
Elec	Jndergrnd/Slab	Reviewed	12/09/22	JKGoschie	Zone 4.
Elec	Jndergrnd/Slab	Reviewed	12/29/22	JKGoschie	Zo9ne 1 Level 3 PT deck.
Elec	Jndergrnd/Slab	Reviewed	01/05/23	JKGoschie	Level 2 zone 3.
Elec	Jndergrnd/Slab	Reviewed	01/23/23	JKGoschie	PT 4.
Elec	Jndergrnd/Slab	Reviewed	01/26/23	JKGoschie	Zone 2 PT#, Zone 4 level 2 PT.
Elec	Jndergrnd/Slab	Reviewed	02/07/23	JKGoschie	Level 3 zone 3. Contractor sent picture for this inspection.
Elec	Jndergrnd/Slab	Reviewed	02/27/23	JKGoschie	PT deck 5 in garage.
Elec	Jndergrnd/Slab	Needed			
	Electrical - Feeder	Needed			
	Electrical Service	Needed			
	ng/Grounding	Reviewed	11/04/22	JKGoschie	3 ground rods at service area.
213 S Bondir	Spec ng/Grounding	Needed			
	Elec Ceiling Cover	Needed			
	Rough Electrical	Reviewed	02/03/23	JKGoschie	Level 1 outside shear wall.
220 R	Rough Electrical	Reviewed	02/15/23	BARichardson	Common wall between fire separation floors 1-5 for wall cover
220 R	Rough Electrical	Cancelled	03/09/23	JKGoschie	

Page 9 of 13 Date: 3/18/2023

	_	Rough Electrical	Needed			
	_	Limited Energy	Needed			
	299	Final Electrical	Needed			
Fire			Active	04/06/22	03/11/24	
	_	ection	Result	Inspected	Inspector	Comment
	849	Final Fire	Needed			
Mech	anica	n l	Active	08/15/22	03/11/24	
		ection	Result	Inspected	Inspector	Comment
	416	Rough Gas Piping	Needed			
	450	Final Gas Piping	Needed			
	420	Rough Mechanical	Needed			
		Final Mechanical	Needed			
Plum			Active	04/06/22	03/11/24	
	Insp	ection	Result	Inspected	Inspector	Comment
	310	Sanitary Sewer	Reviewed	07/28/22	TSHodges	Started construction of public waste manhole. Contractor is building a pour in place manhole. Needs to locate some pipe parts.
	310	Sanitary Sewer	Reviewed	07/29/22	JRLaCasse	Were not ready on first visit-Pictures okay for MH base-sand collars were used
	310	Sanitary Sewer	Reviewed	08/01/22	TSHodges	Need air or water test on waste lateral, set riser clean out inside approved cover and finish new public manhole.
	310	Sanitary Sewer	Needed			
	315	Storm Sewer	Reviewed	06/27/22	JRLaCasse	Tie in to existing catch basin-marked plans
	315	Storm Sewer	Reviewed	06/28/22	JRLaCasse	8" connection stubbed to back of sidewalk to public 24" concrete storm line in middle of street-marked outdated plans
	315	Storm Sewer	Reviewed	10/10/22	JRLaCasse	eastside of courtyard-marked plans
	315	Storm Sewer	Reviewed	10/12/22	TSHodges	Marked plans
	315	Storm Sewer	Reviewed	10/13/22	TSHodges	Marked plans
	315	Storm Sewer	Reviewed	11/02/22	TSHodges	Making connection into public catch basin.
		Storm Sewer	Reviewed	11/07/22	TSHodges	Cleanout required on 10" storm in courtyard near GL - 4. SEK
	315	Storm Sewer	Reviewed	11/08/22	TSHodges	Marked plans.
	315	Storm Sewer	Reviewed	02/03/23	LXNgariki	8" storm line run that connects to public system with 6" directional CO riser and tracer wire. Marked on plans (NE corner of building)
	_	Storm Sewer	Needed			
	318	Under Floor Plumb	Approved	01/05/23	SEKelley	
	320	Rough Plumbing	Cancelled	08/11/22	SEKelley	Needed Underfloor.
	320	Rough Plumbing	Cancelled	10/06/22	SEKelley	Needed Underfloor.
	320	Rough Plumbing	Reviewed	02/02/23	SEKelley	Demising wall between units 132 and 136, DWV and water tests ok, ok to cover.
	320	Rough Plumbing	Reviewed	02/28/23	SEKelley	Units 138 and 239, DWV tests ok. Water lines and tub tests to come.
	320	Rough Plumbing	Reviewed	03/01/23	SEKelley	East shear wall of units 139 and 240, DWV and water tests ok, ok to cover.
	320	Rough Plumbing	Reviewed	03/02/23	SEKelley	DWV and water in shear walls, units 112,113,128, 214, 215 and 230, tests ok, ok to cover.
	320	Rough Plumbing	Reviewed	03/03/23	SEKelley	Units 139 and 240, DWV tests ok. Tubs and water lines still to come.
	320	Rough Plumbing	Reviewed	03/06/23	SEKelley	Units 135, 136, 237 and 238, DWV tests ok. Water lines and tubs to come.

320 Rough Plumbing	Reviewed	03/07/23	SEKelley	Rooms 137-119-221-236-134, DWV test only ok. SEK
320 Rough Plumbing	Reviewed	03/08/23	SEKelley	Units 129, 130, 131, 133, 231, 232, 233, and 235, DWV tests only. Tests ok.
320 Rough Plumbing	Reviewed	03/09/23	SEKelley	Units 127, 128, 132, 229, 230, and 234. DWV tests only, ok.
320 Rough Plumbing	Reviewed	03/10/23	SEKelley	Units 114, 115, 116, 117, 118, 216, 217, 218, 219 and 220. DWV tests only, ok.
320 Rough Plumbing	Reviewed	03/13/23	SEKelley	Rooms 112, 113, 214, and 215. DWV tests only, ok. Water lines and tubs to come.
320 Rough Plumbing	Reviewed	03/16/23	RC Kennedy	Partial on units 341,315.316,331, DWV/H20 in seismic wall. Test ok, ok to cover. RCK
320 Rough Plumbing	Needed			
325 Water Service	Reviewed	01/09/23	RC Kennedy	6" ductile iron stubbed into building, working pressure. Connection to meter to come. RCK
325 Water Service	Needed			
330 Shower Liner	Needed			
335 Backflow Device	Needed			
399 Final Plumbing	Needed			
Public Works	Active	04/06/22	03/11/24	
Inspection	Result	Inspected	Inspector	Comment
725 Stormwater Mgmt Facility	Needed			
735 Stormwater Facility Planting	Needed			
750 R/W Excavation	Needed			
765 Sidewalk	Needed			
775 Drive/Curb Cut	Needed			
799 Final Public Works	Needed			

To request an inspection go to $\frac{https://pdd.eugene-or.gov/BuildingPermits/InspectionLogin}{For more information call 541-682-5283}.$

	FEES			
Fees	Total Due	Amount Paid	Paid Date	Amount Due
Application	\$0.00	\$0.00		\$0.00
Miscellaneous Admin, State	\$0.00	\$0.00		\$0.00
Building	\$103,815.95	\$99,968.59		\$3,847.36
Building Plan Check per Applicant Value	\$25,474.38	\$25,474.38	04/06/22	\$0.00
Supplemental Plan Review, Bldg	\$53.80	\$53.80	04/06/22	\$0.00
Supplemental Plan Review, Bldg	\$161.40	\$0.00		\$161.40
Supplemental Plan Review, Bldg	\$107.60	\$0.00		\$107.60
Supplemental Plan Check, Str. Eng.	\$860.80	\$860.80	04/06/22	\$0.00
Supplemental Plan Check, Str. Eng.	\$322.80	\$322.80	04/06/22	\$0.00
Supplemental Plan Check, Str. Eng.	\$215.20	\$0.00		\$215.20
Supplemental Plan Check, Str. Eng.	\$107.60	\$0.00		\$107.60
Supplemental Plan Check, Str. Eng.	\$161.40	\$0.00		\$161.40
Supplemental Plan Check, Str. Eng.	\$322.80	\$0.00		\$322.80
Supplemental Plan Check, Str. Eng.	\$53.80	\$0.00		\$53.80
Seismic Hazard Fee	\$646.66	\$646.66	04/06/22	\$0.00
Phased Permit Base Fee	\$335.00	\$335.00	04/06/22	\$0.00
Phased Permit Coordination Fee	\$1,500.00	\$1,500.00	04/06/22	\$0.00
Fire Systems Plan Check Fee - Other	\$324.08	\$0.00		\$324.08

Deferred Submittal Plan Check	\$387.41	\$387.41	07/12/22	\$0.00
Deferred Submittal Plan Check	\$1,657.17	\$1,657.17	08/16/22	\$0.00
Deferred Submittal Plan Check	\$337.49	\$0.00		\$337.49
Deferred Submittal Plan Check	\$350.29	\$0.00		\$350.29
Deferred Submittal Plan Check	\$215.25	\$0.00		\$215.25
Deferred Submittal Plan Check	\$286.29	\$0.00		\$286.29
Deferred Submittal Plan Check	\$215.25	\$0.00		\$215.25
Deferred Submittal Plan Check	\$215.25	\$0.00		\$215.25
Deferred Submittal Plan Check	\$215.25	\$0.00		\$215.25
Building Permit Fee per Bldg Div Value	\$39,191.36	\$39,191.36	04/06/22	\$0.00
Fire System Permit Fee - Other	\$498.58	\$0.00		\$498.58
Zoning Plan Check	\$17,636.11	\$17,636.11	04/06/22	\$0.00
State Surcharge, Structural	\$5,040.97	\$5,040.97	04/06/22	\$0.00
State Surcharge, Structural	\$59.83	\$0.00		\$59.83
Building Admin Fee, State	\$2,734.72	\$2,734.72	04/06/22	\$0.00
Building Admin Fee, State	\$0.00	\$0.00		\$0.00
Building Plan Check Admin	\$4,127.41	\$4,127.41	04/06/22	\$0.00
Building Plan Check Admin	\$0.00	\$0.00		\$0.00
Electrical	\$216.35	\$0.00		\$216.35
Supplemental Plan Check, Electrical	\$107.60	\$0.00		\$107.60
Minimum Permit Fee	\$97.10	\$0.00		\$97.10
State Surcharge, Electrical	\$11.65	\$0.00		\$11.65
Electric Plan Check Admin	\$0.00	\$0.00		\$0.00
Electric Admin Fee, State	\$0.00	\$0.00		\$0.00
Fire	\$5,878.65	\$5,878.65		\$0.00
Fire Plan Check	\$5,878.65	\$5,878.65	04/06/22	\$0.00
Fire Plan Check Admin	\$0.00	\$0.00	04/06/22	\$0.00
Mechanical	\$53.80	\$0.00		\$53.80
Supplemental Plan Review, Mechanical	\$53.80	\$0.00		\$53.80
Mechanical Plan Check Admin	\$0.00	\$0.00		\$0.00
Mechanical Admin Fee, State	\$0.00	\$0.00		\$0.00
Plumbing	\$3,152.35	\$3,043.11		\$109.24
Plumbing Plan Check	\$381.33	\$381.33	04/06/22	\$0.00
Supplemental Plan Review, Plumbing	\$107.60	\$107.60	07/12/22	\$0.00
Supplemental Plan Review, Plumbing	\$53.80	\$0.00		\$53.80
Plumbing Fixtures	\$49.50	\$49.50	04/06/22	\$0.00
Plumbing Fixtures	\$717.75	\$717.75	07/12/22	\$0.00
Plumbing Fixtures	\$49.50	\$0.00		\$49.50
Sanitary Sewer Footage	\$149.25	\$149.25	04/06/22	\$0.00
Storm Sewer Footage	\$734.25	\$734.25	04/06/22	\$0.00
Storm Sewer Footage	\$344.25	\$344.25	07/12/22	\$0.00
Water Service Footage	\$119.75	\$119.75	04/06/22	\$0.00
Removal, Abandonment, Cap of Fixture	\$36.75	\$36.75	04/06/22	\$0.00
State Surcharge, Plumbing	\$142.86	\$142.86	04/06/22	\$0.00
State Surcharge, Plumbing	\$127.44	\$127.44	07/12/22	\$0.00
State Surcharge, Plumbing	\$5.94	\$0.00		\$5.94
Plumbing Admin Fee, State	\$98.06	\$98.06	04/06/22	\$0.00
Plumbing Admin Fee, State	\$0.00	\$0.00		\$0.00
Plumbing Plan Check Admin	\$34.32	\$34.32	04/06/22	\$0.00
Plumbing Plan Check Admin	\$0.00	\$0.00		\$0.00
	\$3.30	43.30		Ψ3.30

Public Works	\$6,121.99	\$6,121.99		\$0.00
PW Plan Check, New Commercial	\$954.75	\$954.75	04/06/22	\$0.00
Stormwater Mgmt Facility	\$289.75	\$289.75	04/06/22	\$0.00
R-O-W Excavation (w/ pavement cuts)	\$4,372.00	\$4,372.00	04/06/22	\$0.00
PW Plan Check Admin	\$112.01	\$112.01	04/06/22	\$0.00
PW Admin, Local	\$393.48	\$393.48	04/06/22	\$0.00
Total All Fees	\$119,239.09	\$115,012.34		\$4,226.75